

PERMIT SNAPSHOT REPORT ACST-0225-0285 FOR CITY OF NORTH RICHLAND HILLS

Permit Type Access	ory Structure			Project:				App Date:	02/12/2025	5
Work Class: Carport	t (Residential)			District:	In Jurisdiction	n		Exp Date:	NOT AVAII	LABLE
Status: Resubr	nitted			Square Feet:	0.00			Completed:	NOT COM	PLETED
/aluation: \$0.00				Assigned To	:			Approval		
Description: carport								Expire Date:		
Parcel: P14497		Main	Address: 801 Nrh	3 Mickey St , TX 76182		Mai	in Zone:	R-3(Single Fami	ly)	
Property Owner .arry Fortney 3016 Mickey St. Jorth Richland Hills, 1 Jome: (214) 460-352 Jobile: (214) 460-352	La 80 FX 76182 No 28 Ho	omeowner arry Fortney 016 Mickey S orth Richlan ome: (214) lobile: (214)	d Hills, TX 7618 460-3528	2 North R Home:		3	·			
Permit Custom Field	s									
Description of work	Build/ install	l carport	Lot	Lot ODELL, W E ADDITION Total Block 2 Lot 13R2			N Total	Area sqft. 240		
Estimated Fair Marke Value of Construction	timated Fair Market 1350 Is carport attached or lue of Construction detached to a structure?		to a	Detached	•·=•		Minimum Work ut a Permit	No		
\$525 Work without a Permit Fee	No		Double P	ermit Fee	No					
Invoice No. Fee NOT INVOICED Residentia		l Carport		_			-	Fee Amount \$159.00	Amo	unt Paid \$0.00
				1	Total for Invoice NOT INVOICED Grand Total for Permit		-	\$159.00 \$159.00		\$0.00 \$0.00
Submittal Name Accessory Structure F	Review v.1		Status Not Approved		Received Da 02/12/2025		ue Date 8/04/2025	Complete Date 02/27/2025	Resubmit Yes	Completee Yes
Item Review Name		Departm	ent	Assigned	User	Status		Assigned Date	Due Date	Complete Date
Building Inspections Department		Building Inspections Department		Carranza, I-3408, Michael Requires R		Re-submit	02/12/2025	03/04/2025	02/27/202	
ridge. 2) Common metal 3) Side building lir	at roofs are not l posts are not ne setback is m	permitted. T nin six feet	he structure sha	all have maso	onry or other all			12 horizontal (4:12 / enhanced materia		es of the
/i) nood minimum	on separation		Status		Received Da	ite D	ue Date	Complete Date	Resubmit	Complete
4) need minimum Submittal Name	Review v 2		In Review		03/26/2028		8/31/2025		No	No
Submittal Name		Department		Assigned User Sta		Status		Assigned Date	Due Date	Complete Date
Submittal Name		Departm		Carranza, I-3408, Michael In Review		w	03/26/2025	03/31/2025		
Submittal Name Accessory Structure F		•	Inspections ent	Carranza,	I-3408, Michae					
Submittal Name Accessory Structure F Item Review Name	Department	Building	ent	Carranza, Assigned		Status		Assigned	Due	Complete
Submittal Name Accessory Structure F Item Review Name Building Inspections	Department	Building Departmo Departmo	ent		User		s Re-submit	Assigned Date 03/26/2025	Due Date 03/31/2025	Complete Date 03/31/202

Workflow Step / Action Name	Action Type	Start Date	End Date

PERMIT SNAPSHOT REPORT (ACST-0225-0285)

Review v.1		02/12/2025	0:00		
Accessory Structure Review v.1	Receive Submittal	02/12/2025	0:00	02/27/2025 1	16:35
Accessory Structure Review v.2	Receive Submittal	03/26/2025	0:00		
Invoice Created v.1	Generic Action				
Issue Permit v.1					
Issue Permit v.1	Generic Action				
Building Inspections v.1					
Foundation v.1	Inspection				
Seconds v.1	Inspection				
Final Inspections v.1					
Final Building v.1	Inspection				